



Notes:

1. MAIN DISCONNECT PROVIDED BY OTHERS
2. FIELD WIRING TO BE COPPER RATED FOR 75°C MINIMUM.
3. - - - - INDICATES FIELD WIRING OUTSIDE OF BOX.
4. ALR-1 & ALR-2 PROGRAM NUMBER: 4107 6004 04



AUXILIARY CONTACTS



CONTACTS CLOSED DURING NORMAL OPERATION

FUSE SELECTION (MAX SIZES SHOWN)

FUSE	120V	230V
F1-F4	6.3 AMP	6.3 AMP
F5-F6	1.25 AMP	1.25 AMP

Revised: JAH	Date: 04/15/13	Drawn: JAH	Date: 07/12/12
<small>This drawing and the information contained therein remain the property of BeaconMedics and may not be used for other than the purpose for which it is issued without the expressed written permission from BeaconMedics Engineering.</small>			Scale: NTS
BeaconMedics			D
Description: DWG WIRING CONTROL DX DRYER - DEW POINT (NO CO) 120/240VAC		Part Number: 4107 8540 79	
DN: HOP130457	Rev: 01	Sheet 1 of 1	